



Colibri Scan Report



Nummernschild
GD PT 120
VIN

Datum
12.5.2023 16:18

Kunde
PDR-Team GmbH



Colibri Scan Report

	10	20	30	40	50	60	70	80	Gesamt	
Horizontal	Motorhaube	4	36	53	33	3	4		133	Ø 31 mm
	Dach	11	63	115	70	18	3	2	282	Ø 31 mm
	Heckklappe oben		10	4	1	1	1		17	Ø 28 mm
	Heckklappe unten								0	Ø 0 mm

Nummernschild
GD PT 120



VIN


Datum
12.5.2023 16:18

Kunde
PDR-Team GmbH


Links	Seitenteil vorne	1	11	8	2	1			23	Ø 26 mm
	Tür Vorne	3	8	1		1			13	Ø 21 mm
	Dachholm		8	8	3				19	Ø 27 mm
	Tür Hinten	1	10	12	2	1			26	Ø 27 mm
	Seitenteil hinten	3	6	3	3				15	Ø 24 mm

Rechts	Seitenteil vorne								0	Ø 0 mm
	Tür Vorne		1						1	Ø 20 mm
	Dachholm	3	3	4	4				14	Ø 26 mm
	Tür Hinten	1	4						5	Ø 18 mm
	Seitenteil hinten								0	Ø 0 mm







Seitenteil vorne Links




Seitenteil vorne Rechts




Tür Vorne Links




Tür Vorne Rechts



Tür Hinten Links




Tür Hinten Rechts




Seitenteil hinten Links




Seitenteil hinten Rechts




Dach




Dachholm Links



Dachholm Rechts



Motorhaube



Heckklappe oben

Kein Bild

Heckklappe unten